

H&L's Cat Style HL-103-8115
Rippers are produced from
Chrom-Moly-Nickel grade alloy
steels to enhance shank
DURABILITY and
TOUGHNESS!

HL-6Y-8960 Wear Plate with one HL-6Y-1204 with HL-6Y-1202 Pin and Retainer 3.88" 21.35" 120 1.31" Diameter Thru 2.88 Counterbore 2 Locations

Uses (R500) HL-4T-4502ST-4R Tooth with HL-6Y-1204 and HL-6Y-1202 Pin and Retainer

Note: Nosepiece HL-103-8115 and HL-103-8115B are the same size and construction

ORIGINAL PRODUCT

H&L® TOOTH COMPANY

Factory Direct Made in Tulsa, Oklahoma

HL-103-8115

Ripper Repair Nosepiece 160.0#/72.58kgs. H&L Tooth Company History since 1931:

This H&L's Cat style HL-103-8115 ripper repair nosepiece is a replacement for Caterpillar's 4.00" thick rippers on Model D10N, D10T and D9L Dozers. This nosepiece uses the H&L's R-500 Series tooth system. Ripper nosepiece was engineered and introduced by the H&L Tooth Company in 1994.

H&L products meet or exceeds all OEM standards.